





516 010 0003/HD 31201485

Ball joint to fit

Volvo S60, V70 II Kombi, XC90, XC70 Cross Country





Ball joints fail prematurely due to heavy load

Effect

- Noise from the front end
- Impaired driving safety





- Use of extremely long-wearing plastic ball joint sockets (in aviation tried and tested material)
- MEYLE high-tech grease

Advantage

Quality, long-life ball joints